SFCRFT Approved For Release 2002/01/25 : CIA-RDP72-00341R006100080126-6

DIARY NOTES

DD/S

7 July 1966

* * * * * * * * *

1. Light Switches in Headquarters Building: There have been several conversations on the defective light switches in Headquarters building and the agreement by all concerned is that corrective action is necessary. Jack Blake advised that perhaps we have a quick solution to this problem which will provide correction and protect against the high voltage involved. This is an extremely dangerous situation and we should move quickly to ensure that corrective action 25X1A is taken. (Action with



RLB:jvw

* Extract to A-D/Sec on 15 Jul 66

25X1A